

The application of 4M change

Supplier: Zhe Jiang Rectron Electronic Co., Ltd

Date: 2016-07-01

Item	RBUM , RS4M , RS6M package (封装)	Supplier					
P/N	RBU4M, RBU6M, RBU8M, RBU10M, RBU15M, RS4M, RS6M, RS8M, RS10M, RS15M, RS20M, RS25M, RS35M related series part no (相关料号)	GM	SALE	PURCHASE	PE	QRA	Prepared
		刘德明	刘年富	陆良宏	金少伟	周松	周松

Class. Material Machine/Tooling Method Manufacture site
 Man


Change Effect Level High Low

Description:


因油墨印字偶有印字不牢，印字不全，过炉后印字脱落等情况，我司故将此三种主要桥式封装产品全部改成由油墨印字改成镭射印字，新货将从8月份（第30周）开始供应，起始产品周期从VG30开始

Due poor marking (like incomplete marking, fall off after soldering) defective issue had been happen in ink marking bridge rectifier products, so RECTRON will change from ink marking to laser marking. the first starting D/C (producing data code) will begin from VG30

Content (Before) :



Content (After) :



The date of sample: From VG30

Product stage: Mass

Sample Q'ty :

Pcs

Customer Approved

Customer opinion:

Approved: Yes () No ()

Approved date by customer: